



RCC Pilotage Foundation Mediterranean Spain

1st Combined Edition 2017
ISBN 978 184623 650 1

Supplement No.3
April 2019



Caution

Whilst the RCC Pilotage Foundation, the author and the publishers have used reasonable endeavours to ensure the accuracy of the contents of this book, it contains selected information and thus is not definitive. It does not contain all known information on the subject in hand and should not be relied upon alone for navigational use: it should only be used in conjunction with official hydrographical data. This is particularly relevant to the plans, which should not be used for navigation. The RCC Pilotage Foundation, the author and the publishers believe that the information which they have included is a useful aid to prudent navigation, but the safety of a vessel depends, ultimately, on the judgment of the skipper, who should access all information, published or unpublished. The information provided in this book may be out of date and may be changed or updated without notice. The RCC Pilotage Foundation cannot accept liability for any error, omission or failure to update such information. To the extent permitted by law, the RCC Pilotage Foundation, the author and the publishers do not accept liability for any loss and/or damage, howsoever caused, that may arise from reliance on information contained in these pages.

This supplement contains amendments and corrections sent in by a number of cruising yachtsmen and women, in addition to those culled from official sources such as Notices to Mariners.

Positions and waypoints

All positions and waypoints are to datum WGS84. They are included to help locating place, features and transits. Do not rely on them alone for safe navigation.

Bearings and lights

Any bearings are given in degrees True and from seaward. The characteristics of lights may be changed during the lifetime of this book and they should be checked against the latest edition of the UK Admiralty List of Lights.

Note Where lights have been modified in the text do please remember to alter them on the appropriate plan(s).

This supplement is cumulative and the latest information is marked in **blue**.

For 2018 thanks due to:
Pierick Petain, John Iliff

For 2019 thanks due to:
John Costin

Contents

iv. Amend *Cabo de la Nao* to *Cabo de San Antonio* and *Islotes Columbretes* to *Río Ebto* to *Castellón de Plana* to *Vinaros*.
v. Amend *Río Ebro* to *Torredembarra* to *Alcanar* to *Tarragona*.

Page 5 Official Addresses

See Appendix IX (not VIII)

Page 8 Harbours, marinas and anchorages Port Communications

In all port boxes, if an eppa.es website is given, replace it with www.puertosdeandalucia.es. Click on Puertos/Ports and select the relevant port.

Page 13 Western Mediterranean weather

See Appendix IV (not III)

Page 33 Gibraltar

Repair facilities Amend website to

www.electromedmarine.com

Engineers Amend website to www.electromedmarine.com

and email to service@electromedmarine.com

Page 40 Puerto de La Atunara

Delete website.

Page 43 Puerto de la Duquesa

Delete [duquesa.htm](#)

Page 52 Marina de Bajadilla

Port Communications

Amend website to www.puertosdeandalucia.es click on Puertos/Ports and select the relevant port.

Page 59 Málaga Port

The Real Club Mediterraneo de Málaga now welcomes visiting yachtsmen.

Page 161 Marina Greenwich

It is reported that Marina Greenwich, though usefully situated on the Greenwich meridian, nevertheless leaves much to be desired in the shore facilities provided, the cost of an overnight stay was reported as being significantly higher than any other marina experienced in a lengthy cruise.

Page 62 Puerto Caleta de Vélez

Delete www.eppa.es website, replace with www.puertosdeandalucia.es

Page 68 Puerto de Motril

Amend website from .com to .es

Page 71 & 77 Port Communications

Add to contacts www.puertosdeandalucia.es.

Page 73 Adra

Berths - marina Berths now have electricity and water, otherwise unmanaged.

Pages 95, 97, 99, 100 Port Communications

Amend www.eppa.es to www.puertosdeandalucia.es

Page 124 Mar de Cristal, Mar de Menor

Now much updated. Finger pontoons for 120 boats up to 15m. All facilities.

Page 140 Port Communications

Delete website.

Page 171 Cala Sardinera

Anchorage to NW now has mooring buoy, beware confusing it with a beach buoy!

Page 192 Port Communications

Amend website to www.rcnv.es

Page 194 Port Communications

Delete website

Page 205 Isolated and impressive islands

Amend park website to www.parquenaturales.gva.es

Page 226 Port Communications

Delete website

Page 230 Sant Carles Marina

Club Náutico de Sant Carles Yacht Harbour (west)

Amend website to <http://clubnauticlarapita.com>.

Page 277 Port Communications

Change Marina Port Vell website to www.oneoceanportvell.com

Page 310 Port Communications

Amend email to info@cnsfg.cat

Amend website to <http://cnsfg.cat/ca>

Page 376 Puerto de Llança plan

New outer breakwater, see plan below.

Page 387 II. Charts

Change UKHO website to www.admiralty.co.uk

Chart agents

Change Gibraltar Chart Agency contact details to +350 123456

email@gibraltarchartagency.com

www.gibraltarchartagency.com

